Annexure D

BUILDING SAFETY CERTIFICATE

No. 721 Dated: 2016/29				
It is certified that the existing building	it. Anne's C	Convent School	ol, Mordinam	e of the
building or premises) at Monday, Rance	hi - 83 521	4		
(address) is having bloc				
Detail of Block(s) in Block Block	Block	Block	Block	Block
school (1) (2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the				
Block				
The building is owned/occupied bySt	Anne's Conve	ent School,	, Mandaez	(name
of the Institution) have complied with the Bu	uilding safety requ	irements in acc	ordance with	National
Building code Rules, and verified by the offi	cers concerned of	BUD Kunch	A	(Name of
Department/ Govt.) on15 06 20	4. (date of in	spection) in	the prese	ence of
Alaexiya Beck , Principa	is is industrian	(name and	addresses	or the
Manager/Secretary or his representative) a running school with effect from .19.1.06.20	and that the build	5 upos /F	TIT TOR OCCUP	cordance
with rule and subject to compliance of the sp	ecific conditions as	appended.	production and	
1 Rama available				
2. CLUSH Toilet Freely floor)¥			
2. CWSN Toilet Every floor 3. Boy's And Girds Toilet & 4. Pucca Boundary Issued on 20.04.24 at Bar	very floor			
4. Pucca Boundary D	10			
Issued on 20.04.24 at	ichi by			
* Strike out whichever is not applicable. In		more than six ι	ise separate	sheet for
detail.			o voto	16/2/02/4
	Sign	ature with Seal :	rentive En	dinect
1	4	Name Name	BCJ No -	1
	N 0 A-J-	resignation	ont/ Office:	<u>nent</u>
66 D 2 7 A	Name & Add	ress of Departm	enio Onice	